






D Návod na montáž hliníkových základov pre skleník s 2 až 6 poľami



Kusovník				Dĺžka	2 polia	3 polia					
Pol.	Tvar	Označenie	Č. tovaru	(v mm)	Kusov	Kusov	Č. tovaru	Dĺžka	4 polia	5 polí	6 polí
1		Základový profil	9291606	1540	2	-	9291605	1500	4	2	-
		Strana 111 x 25 mm	9291615	2280	-	2	9291612	2240	-	2	4
2		Základový profil Predná a zadná stena 111 x 25 mm	9291609	2220	2	2			2	2	2
3		Rohový uholník 110 x 30 x 30 x 1,5 mm	9291773		4	4			4	4	4
4		Upevňovací uholník 136 x 25 x 20 x 1,5 mm	9291776		6	8			10	12	14
5		Spojka vzpier	9291694		-	-			4	4	4
6		rutky M6 x 10	9291733		28	32			36	40	44
7		atica M6 s prírubou	9291736		34	40			58	64	70
8		Rhombus skrutka M6 x 12 - na upevnenie skleníka (podlahový profil) k základu	9291739		6	8			10	12	14




1 + 2 = dávajte pozor na zadnú stranu!



Gutta Werke GmbH
info@gutta.com
www.gutta.com
Servisný telefón 09001/200007 (99 centov/min.)



1



2

